

FEB 08 1982

DPM 5315

MCDONNELL DOUGLAS CORPORATION

U.S. DEPARTMENT OF LABOR
WORKPLACE STANDARDS ADMINISTRATION
BUREAU OF LABOR STANDARDS
MATERIAL SAFETY DATA SHEET

FORM NO. OSHA-20 (MODIFIED)
MAY 1971

MDC CONTROL NO.

SECTION I: MATERIAL AND MANUFACTURER IDENTIFICATION

MANUFACTURER'S NAME

Jensco Co.

EMERGENCY TELEPHONE NO.

(213) 541-4237

ADDRESS (NUMBER, STREET, CITY, STATE AND ZIP CODE)

2565 Palos Verdes Drive West

CHEMICAL NAME AND SYNONYMS

Palos Verdes, CA. 90274

TRADE NAME AND SYNONYMS

Jensco Silicone Rubber Cleaner #192

CHEMICAL FAMILY

FORMULA

SECTION II: HAZARDOUS INGREDIENTS*

PAINTS, PRESERVATIVES/SOLVENTS	%	TLV (UNITS)	ALLOYS AND METALLIC COATINGS	%	TLV (UNITS)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					

HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES*

Glycol Ether EB

000111-76-2

15-20

TLV (UNITS)

Ac61H
25 ppm

Water

80-85

SECTION III: PHYSICAL DATA

BOILING POINT (°F)	205	SPECIFIC GRAVITY (H ₂ O = 1)	
VAPOR PRESSURE (mm Hg.)		PERCENT VOLATILE BY VOLUME (%)	100
VAPOR DENSITY (AIR = 1)		EVAPORATION RATE	
SOLUBILITY IN WATER	complete		

APPEARANCE AND ODOR

Clear to amber with some odor

SECTION IV: FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (METHOD USED)	non-flammable	FLAMMABLE LIMITS	
EXTINGUISHING MEDIA			
SPECIAL FIRE FIGHTING PROCEDURES	N/A		

UNUSUAL FIRE AND EXPLOSION HAZARDS

*PLEASE DO NOT USE GENERALIZATIONS, SUCH AS PETROLEUM HYDROCARBONS, ALCOHOL, KETONES.
USE SPECIFIC CHEMICAL NAMES, SUCH AS METHANOL, BENZENE, PERCHLOROETHYLENE.

MDC 363(20-SEP 71)

BOE-C6-0202269

SECTION V: HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE

EFFECTS OF OVEREXPOSURE

Remove to fresh air

EMERGENCY AND FIRST AID PROCEDURES

Eyes-flush eyes at once with plenty of water for at least 15 minutes.

Skin-wash with soap and water. Inhalation-Breathe fresh air.

Ingestion-Give large quantities of water and call a physician

SECTION VI: REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE		

INCOMPATIBILITY (MATERIALS TO AVOID)

HAZARDOUS DECOMPOSITION PRODUCTS

HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR		

SECTION VII: SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Remove excess. Rinse thoroughly. Repeat if necessary

WASTE DISPOSAL METHOD

Land burial or as permitted by governing agencies

SECTION VIII: SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (SPECIFY TYPE)

VENTILATION	LOCAL EXHAUST Use adequate ventilation	SPECIAL
	MECHANICAL (GENERAL)	OTHER

PROTECTIVE GLOVES

Rubber gloves

EYE PROTECTION

Goggles

OTHER PROTECTIVE EQUIPMENT

Rubber apron

SECTION IX: SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Keep out of sun and away from heat

OTHER PRECAUTIONS

Avoid contact with skin and eyes

PREPARED BY

Don Jensen, President

June 30, 1981

DATE